```
04/13/2024
    [c] 6.10.86.1301
    [+] Increased polling interval for older control units, for example SRS IDECU 7000.
 3
    The maximum exchange rate with the unit is approximately 1 op/sec.
     [+] For control units with a bitrate below 100 baud, the delay for communication is
 4
     300 ms
 5
     [+] Setting the exchange rate for protocols has been moved to the technical
    parameters section. It is not recommended to change unless necessary.
 6
 7
     03/31/2024
8
     [c] 6.10.85.1298
9
     [!DB] Correcting errors in the database
10
    [+]Adding a control interval after reading identifiers via the MMC SCI protocol
11
12
    04/27/2023
13
    [c] 6.10.84.1294
    [!] Russian language by default on first launch
14
15
     [!DB] Fix in ABS error codes
    [!] Correction of the time grid on charts
16
17
18
    20.12.2022
19
    [v] 6.10.83.1281
20
    [!] Fixed selection of a directory for storing logs
21
    [!] Added ability to ignore ISO-9141 connections for cars before 2000
22
23
    01.10.2022
2.4
    [v] 6.10.82.1281
25
    [!] Fixed state of the "stop" button in a new session
26
    [!] Fixed initialization of the table of error codes, which led to the expansion of
    service information.
27
    [!] Stopping the session by the user is no longer accompanied by a preliminary
    warning about the loss of connection
28
29
    09/27/2022
    [v] 6.10.81.1277
30
31
     [!] Updated help
32
     [-] Removed automatic adjustment of polling rate on charts
    [!] Enabled ignoring the response of the commission for the conclusion of tests
33
     according to the old protocols
34
    09/17/2022
35
36
     [v] 6.10.80.1271
     [!] Added manual option for selecting a COM port for the adapter
37
     [!] Changing the firmware of the MMC K-Line Advanced adapter
38
     [!] The driver for the MMC K-Line Advanced adapter is included in the executable file
39
40
     [-] Manual change of speed in charts is removed, only profit is left
41
    [+] Added increased speed on the options tab
42
43
    09/10/2022
44
    [v] 6.10.79.1256
     [!] Fixed interface for Windows XP
45
46
     [!] Fixed auto-detection of MMC K-Line Advanced adapter based on CH340 chip on
    Windows XP, Windows 7
47
    [!] Bitrate search everywhere is done in descending order
48
    04.09.2022
49
     [v] 6.10.78.1256
50
     [!] Testing of the MMC K-Line Advanced adapter based on the CH9340 chip (designed to
51
    work on Windows 10 only)
52
     [!] The logic for bypassing all possible bitrates - from higher to lower - has been
    changed for the MMC K-Line Advanced adapter
53
54
     08/21/2022
55
    [+] Added auto speed for charts
56
57
    08/07/2022
58
    [v] 6.10.77.1217
    [-] Disabled support for K-Line adapters of all types
59
60
    [-] Disabled support for J2534 adapters
61
    [-] Removed technical logging
```

62

[-] Checking for new versions has been abolished

- [-] Removed sending technical information to developers
- [-] Removed graphics performance check
- 65 [-] The built-in ability to update the software of MMC-Wireless adapters has been removed
- 66 [-] Exporting reports in MS Excel format has been removed
- [!] The software is delivered as a single executable file and can be run from 67 anywhere on the disk
- 68 [-] Removed control panel for protocol technical settings

69

- 70 ;history.txt - version history file
- 71 ;[+] - additions
- ;[!] changes
 ;[v] version 72
- 73