

; history.txt - the version history file
; [+] - add
; [!] - changes
; [v] - version
; [+db] - additions to the database (DB)
; [!db] - changes in the database
; [-bd] - database optimization

02/03/2023

[v] 6.12.62.907

[!] Improved an error on detection adapter MMC Wireless hw 4.1

01/07/2023

[v] 6.12.61.880

[-] Built-in midas.dll library

[!db] Database updated, new error codes added

[!] Updated firmware versions: HW-2 v55.bin; HW-3 v05.bin

[+] Added legend for error code types: Stored, Pending

[+] Added a column with the error type on the DTC tab: Stored, Pending

01/05/2023

[+db] Updated database

[-] Removed the function of sending logs to cloud storage

[!] Only support for MMC-Wireless adapters is left